



Printable - Design Quick Guide

*Print this document out at 100% (Do not scale)

Font Sizes

Screen Printed
Minimum Font Size= 5 point

5 POINT BOLD
6 POINT BOLD
7 POINT BOLD
8 POINT BOLD
10 POINT BOLD
12 POINT BOLD

Radii

- .030"
- .060"
- .100"
- .125"
- .150"
- .200"
- .250"

Hole Diameters

.007" .050"





Screen Printed Minimum Line Thickness Screen Printed Minimum Border Thickness

SCALE= 100%

Keep critical graphics away from cut edges by a minimum of .030"



Fraction	Decimal	Millimeters	Fraction	Decimal	Millimeters
1/64	.0156	.396	33/64	.5156	13.096
1/32	.0312	.793	17/32	.5312	13.493
3/64	.0469	1.190	35/64	.5469	13.890
1/16	.0625	1.587	9/16	.5625	14.287
5/64	.0781	1.984	37/64	.5781	14.684
3/32	.0937	2.381	19/32	.5937	15.081
7/64	.1094	2.778	39/64	.6094	15.478
1/8	.125	3.175	5/8	.625	15.875
9/64	.1406	3.571	41/64	.6406	16.271
5/32	.1562	3.968	21/32	.6562	16.668
11/64	.1719	4.365	43/64	.6719	17.065
3/16	.1875	4.762	11/16	.6875	17.462
13/64	.2031	5.159	45/64	.7031	17.859
7/32	.2187	5.556	23/32	.7187	18.256
15/64	.2344	5.953	47/64	.7344	18.653
1/4	.25	6.350	3/4	.75	19.050
17/64	.2656	6.746	49/64	.7656	19.446
9/32	.2812	7.143	25/32	.7812	19.843
19/64	.2969	7.540	51/64	.7969	20.240
5/16	.3125	7.937	13/16	.8125	20.637
21/64	.3281	8.334	53/64	.8281	21.034
11/32	.3437	8.731	27/32	.8437	21.431
23/64	.3594	9.128	55/64	.8594	21.828
3/8	.375	9.525	7/8	.875	22.225
25/64	.3906	9.921	57/64	.8906	22.621
13/32	.4062	10.318	29/32	.9062	23.018
27/64	.4219	10.715	59/64	.9219	23.415
7/16	.4375	11.112	15/16	.9375	23.812
29/64	.4531	11.509	61/64	.9531	24.209
15/32	.4687	11.906	31/32	.9687	24.606
31/64	.4844	12.303	63/64	.9844	25.003
1/2	.500	12.700	1	1.000	25.400

10 mm
12 mm
16 mm
20 mm

Metal Dome Sizes

Convert inches to millimeters: Multiply by 25.4
Convert millimeters to inches: Multiply by .0394



File Formats

